

# GTI SERVICE NOTE

GTI 107

MAY, 2010

## GPN1000 and SERIES 2XXX FIRMWARE CHANGES

The following is a list of firmware changes that have been implemented on new production GTI GPN1000 and Series 2XXX panels effective May 17, 2010:

The **CONTROL** and **FAULT** relays will open on both a fault and control off condition

The Bi-Fuel delay timer has been modified from 60-seconds to 1-second minimum

The following changes have been implemented on the data logging feature:

- o The time between data snap shots has been reduced from 5-minutes to 1-minute
- o Data logs will now be retained through a power cycle of the GPN panel
- o Data logging will cease any time the Bi-Fuel is OFF, either as a result of a control set point violation or fault condition