## ALTRONIC SERVICE BULLETIN #091523B

Issued: 09/15/2023

## DE-4000 Class B and Class C Timer

Firmware labeled 2.2.X (2.2.0 thru 2.2.4) has an issue when using Class B or C shutdowns for high shutdowns. Also, you will not be able to select the B Timer to start by "State 3 Start" or earlier labeled "Crank". Use only the "Start Button" or "Crank RPM" for the B Timer for these firmware versions. (Low shutdowns are not affected with either situation.)

The next release, 3.0.0, will have the solution where B & C Shutdowns can be used and "State 3 Start" can be used to start the timers for all shutdowns including high.