

# SERVICE BULLETIN

Issued: 4/07/26

TO: ALTRONIC DISTRIBUTOR PARTNERS

FROM: D. BELL – SENIOR VICE PRESIDENT – AFTERMARKET SALES AND SERVICE

SUBJECT: ALTRONIC V-NG UPDATE

A new stator winding is being introduced for the Altronic V-NG units. Part no. 571011F is designed to provide improved output at engine cranking speeds and associated enhanced starting performance.

#### NEW ALTRONIC V-NG UNITS:

Starting with S/N 3550 all new Altronic V-NG units from the factory will be supplied with stator 571011F.

#### SERVICE INSTRUCTIONS FOR EARLIER ALTRONIC V-NG UNITS:

1. To improve starting performance, replace the stator with part no. 571011F.
2. When replacement of the stator is required, use part no. 571011F.

NOTE: DO NOT use stator 571011F in the legacy Altronic V units. These continue to use stator 571003F.

Please refer to the attached updated Service Manual for additional details. This has also been updated on the Altronic website.

# ALTRONIC